**Step 1**：You should DIY a upgrade cable for Smart.Port according to the schematic. This is Frsky Smart.Port cable and FUC-3 below :

Step 2: Change pin sequence, and remove the 5V pin.

Step 3: Plug the "Ground" and "Smart.Port" pin to the back of the Taranis like this.

4.GND(Brown)
5.S.port(Yellow)

Step 4: open "frsky_update_Sport.exe". Choose the right com and select the .frk file.

Step 5: Power the radio on and ensure the internal RF module is powered.
Step 6: If "device is found" ,Click "Download" .
if not, repeat Step 4 and Step 5.

Step 7: "Firmware is updated" , you have your XJT upgraded.